

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/11/2018

Submitted Date:

07/13/2018

Document Number:

691200246**FIELD INSPECTION FORM**
 Loc ID 306310 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1001 17TH STREET #2000City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
,		cogccinspections@gwogco.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287758	WELL	PR	02/01/2018	GW	123-24410	CACHE 8-13	SI

General Comment:

Location**Lease Road:**

Type	Main		
comment:	Main road to Cache 8-34 (API# 05-123-24412), Cache 8-13 (API# 05-123-24410), Cache 8-23 (API# 05-123-24411), Cache 8-24 (API# 05-123-25427), Cache 8-33 (API# 05-123-25665), Cornish 8-53 (API# 05-123-32190) is adequate.		
Corrective ActionL		Date:	
Type	Access		
comment:	Access road to Cache 8-13 (API# 05-123-24410) is adequate. 2-Track Ag road.		
Corrective ActionL		Date:	

Overall Good: ☒**Emergency Contact Number:**

Comment:	No emergency contact number at wellhead.		
Corrective Action:	Install sign to comply with rule 210.b.		Date: 08/13/2018

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Cache 8-13 (API# 05-123-24410) has iron panel fencing.		
Corrective Action:		Date:	
Type			
Comment:	Refer to FIR# 691200244 for additional fencing list for this facility.		
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type:	#		
Comment:	Refer to FIR# 691200244 for complete equipment list for this facility.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.499062,-104.461664
Comment:	This centralized battery serves 6 locations (306312, 306310, 306311, 309823, 309973, 419186). Refer to FIR# 691200244 for Tanks & Berms info regarding this facility.				
Corrective Action:				Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 287758 Type: WELL API Number: 123-24410 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Well appears to be SI at separator.

Corrective Action: _____ Date: _____

BradenHeadComment: Bradenhead appears to be plumbed to surface.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
New Cache FH # 8-32D (API# 05-123-36968), New Cache FH # 8-12D (API# 05-123-36969), New Cache FH # 8-33D (API# 05-123-36970) have never been drilled.	evinsb	07/13/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401703019	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4523576
691200248	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4523572