



Photo 1. View of the project area from the northern edge facing enter. Photos taken before mowing herbicide weed treatments.



Photo 2. View of the eastern portion of the project area from the northern edge facing southward. Green vegetation is largely Russian knapweed (*Rhaponticum repens*).



Photo 3. View of erosional channels forming within the northern portion of the project area where stormwater flows from the access road run onto the well pad.