

Inspection Photos

07/19/2018

Operator: RED HAWK PETROLEUM LLC - 10503

Location ID: 438327

Inspection Doc. Number: 682503634

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: RED HAWK PETROLEUM LLC - 10503
Location ID: 438327



Photo 1: Photo taken from the access road, on the south end of the location, facing west. Photos 1-4 provide an overview of the location from west, northwest, northeast, to east.



Photo 2:

Inspection Photos
Operator: RED HAWK PETROLEUM LLC - 10503
Location ID: 438327



Photo 3:



Photo 4:

Inspection Photos
Operator: RED HAWK PETROLEUM LLC - 10503
Location ID: 438327



Photo 5: Photo taken from the ditch on the east end of the location. Photo of equipment/trash debris that needs to be removed and properly stored or disposed.



Photo 6: Photo taken from the south end of the location. Photo of equipment/trash debris that needs to be removed and properly stored or disposed.

Inspection Photos
Operator: RED HAWK PETROLEUM LLC - 10503
Location ID: 438327



Photo 7: Photo taken from the south end of the location. Photo of equipment/trash debris that needs to be removed and properly stored or disposed.



Photo 8: Photo taken from the south end of the location. Photo of equipment/trash debris that needs to be removed and properly stored or disposed.

Inspection Photos
Operator: RED HAWK PETROLEUM LLC - 10503
Location ID: 438327



Photo 9: Photo taken from the west end of the location. Photo of equipment/trash debris that needs to be removed and properly stored or disposed.



Photo 10: Photo taken from the west end of the location. Photo shows erosion degradation on the slopes. These concerns will be mitigated during interim reclamation.

Inspection Photos
Operator: RED HAWK PETROLEUM LLC - 10503
Location ID: 438327



Photo 11: Photo taken from the south end of the location. Photo shows erosion degradation on the slopes. These concerns will be mitigated during interim reclamation.



Photo 12: Photo taken from the south end of the location. Photo shows erosion degradation on the slopes. These concerns will be mitigated during interim reclamation.

Inspection Photos
Operator: RED HAWK PETROLEUM LLC - 10503
Location ID: 438327



Photo 13: Photo taken from the topsoil berm on the northwest corner of the location, facing southeast. Photo shows areas on the west end of the location that do not appear to be necessary for production operations. These areas need to be reclaimed in accordance to COGCC 1003 interim reclamation requirements.



Photo 14: Photo taken from the topsoil berm on the southwest corner of the location, facing north. Photo of topsoil berm. Photo also shows areas on the west end of the location that do not appear to be necessary for production operations.

Inspection Photos
Operator: RED HAWK PETROLEUM LLC - 10503
Location ID: 438327



Photo 15: Photo taken from the topsoil berm on the southwest corner of the location, facing northeast. Photo shows areas on the west end of the location that do not appear to be necessary for production operations. These areas need to be reclaimed in accordance to COGCC 1003 interim reclamation requirements.



Photo 16: Photo taken from the topsoil berm on the southwest corner of the location, facing east. Photo shows areas on the west end of the location that do not appear to be necessary for production operations. These areas need to be reclaimed in accordance to COGCC 1003 interim reclamation requirements.



Photo 17: 2017 COGIS aerial imagery. Photo shows areas on the west end of the location that do not appear to be necessary for production operations. These areas need to be reclaimed in accordance to COGCC 1003 interim reclamation requirements.