

Inspection Photos  
Location Name: UPRR 43 PAN AM I 29  
Facility ID: 242097



Photo 1. Wellhead



Photo 2. Stained soil near pump jack prime mover