

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/19/2018

Submitted Date:

07/20/2018

Document Number:

688800226**FIELD INSPECTION FORM**Loc ID 325651 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 96735Name of Operator: WILLIFORD RESOURCES, L.L.C.Address: 6506 S LEWIS AVE STE 102City: TULSA State: OK Zip: 74136**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☐
- FOLLOW UP INSPECTION REQUIRED
- 
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Stevens, Glenn	970-749-0192	glennstevens@centurylink.net	<a href="#">SW Inspection Reports</a>
Fischer, Alex		alex.fischer@state.co.us	
Callahan, Linda	918-749-8828	lcallahan3@swbell.net	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215170	WELL	PR	05/28/2003	OW	067-06775	SCHMITT 3-36	EI

**General Comment:**

On July 19, 2018 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Williford Resources Schmitt #3 -36. For the most recent field inspection report of this facility, please refer to document #688800011.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Free standing sign near pump jack.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Free standing sign near tank battery.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Posted on location sign and tank battery sign.		
Corrective Action:		Date:	

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	T post and wire fencing around pump jack and well head.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 2		
Comment:	Drop out tanks for gas supply lines.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Natural gas powered.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		37.140512,-108.098871

Comment:		
Corrective Action:		Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On July 19, 2018 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Williford Resources Schmitt #3-36. For the most recent field inspection report of this facility, please refer to document #688800011. Corrective actions noted in that document have been addressed.	hughesj	07/20/2018

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800227	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4529325">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4529325</a>