

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/19/2018

Submitted Date:

07/23/2018

Document Number:

687902852**FIELD INSPECTION FORM**

Loc ID 333685 Inspector Name: DURAN, JOHN On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10084Name of Operator: PIONEER NATURAL RESOURCES USA INCAddress: 5205 N O'CONNOR BLVD STE 200City: IRVING State: TX Zip: 75039**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.co m	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257589	WELL	PR	07/12/2007	GW	071-07027	HEYDEN 11-22	PR
298096	WELL	AL	06/21/2010	LO	071-09656	Heyden 11-22 Tr	AL

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Pipe and metal debris on site.		
Corrective Action:	Equipment not in use need to be taken off site.	Date:	08/23/2018

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 5		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electrical boxes		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	257589	Type:	WELL	API Number:	071-07027	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	298096	Type:	WELL	API Number:	071-09656	Status:	AL	Insp. Status:	AL

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: c**Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: NO2+ feet Freeboard: YESComment: 30' x 70', No 2+ ft Freeboard marker.Corrective Action: Date: 08/23/2018

Permit:	Facility ID	Permit Num	Expiration Date
	260379	200017289	<input type="text"/>

Monitoring:	Monitoring Type	Comment`
	None	<input type="text"/>

COGCC Comments

Comment	User	Date
<u>SEE : Good Housekeeping : Pipe and metal debris. SEE : Pits : No Freeboard marker.</u>	duranj	07/23/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687902853	Lease sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4530798
687902854	Well pad	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4530799

687902855	Pipe and metal debris	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4530800
-----------	-----------------------	---

