

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/23/2018

Submitted Date:

07/23/2018

Document Number:

689301576

**FIELD INSPECTION FORM**

Loc ID 335396 Inspector Name: Holtz, Darin On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: PO BOX 370  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

10 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Rocky, TEP		COGCCInspectionReports@terraep.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276956	WELL	PR	08/29/2005	OW	045-10575	FEDERAL RWF 424-19	PR
276958	WELL	PR	09/21/2005	OW	045-10574	FEDERAL RWF 324-19	PR
276961	WELL	PR	09/16/2005	OW	045-10573	FEDERAL RWF 24-19	PR

**General Comment:**

[Routine Field Inspection](#)

Location						
<b>Lease Road:</b>						
Type	Access					
comment:						
Corrective Action					Date:	
Overall Good: <input checked="" type="checkbox"/>						
Emergency Contact Number:						
Comment:	1-970-285-9377					
Corrective Action:					Date:	
<b>Good Housekeeping:</b>						
Type	WEEDS					
Comment:						
Corrective Action:					Date:	
Type	TRASH					
Comment:						
Corrective Action:					Date:	
Type	DEBRIS					
Comment:						
Corrective Action:					Date:	
Overall Good: <input checked="" type="checkbox"/>						
<b>Spills:</b>						
Type	Area	Volume				
In Containment: No						
Comment:						
<input type="checkbox"/> Multiple Spills and Releases?						
<b>Fencing/:</b>						
Type	SEPARATOR					
Comment:	Hog panel fencing					
Corrective Action:					Date:	
Type	WELLHEAD					
Comment:	Hog panel fencing					
Corrective Action:					Date:	
Type	TANK BATTERY					
Comment:	Hog panel fencing					
Corrective Action:					Date:	
<b>Equipment:</b>						
Type: Deadman # & Marked	# 4				corrective date	
Comment:						
Corrective Action:					Date:	

Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLs	STEEL AST		,
Comment:	Centralized Battery				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 276956 Type: WELL API Number: 045-10575 Status: PR Insp. Status: PR

**Producing Well**

Comment: Well Producing on plunger lift

Corrective Action:

Date:

Facility ID: 276958 Type: WELL API Number: 045-10574 Status: PR Insp. Status: PR

**Producing Well**

Comment: Well Producing on plunger lift

Corrective Action:

Date:

Facility ID: 276961 Type: WELL API Number: 045-10573 Status: PR Insp. Status: PR

**Producing Well**

Comment: Well Producing on plunger lift

Corrective Action:

Date:

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:  Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Seeding						
		Compaction				
		Gravel				
Berms						

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689301577	Inspection photo 689301577	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4530966">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4530966</a>