

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/16/2018

Submitted Date:

07/17/2018

Document Number:

687902798**FIELD INSPECTION FORM**

Loc ID 333902 Inspector Name: DURAN, JOHN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10084Name of Operator: PIONEER NATURAL RESOURCES USA INCAddress: 5205 N O'CONNOR BLVD STE 200City: IRVING State: TX Zip: 75039**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266468	WELL	PR	03/14/2004	GW	071-07824	PANORAMA 13-11	PR
269669	WELL	PR	08/29/2004	GW	071-07922	PANORAMA 13-11 TR	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Progressive Cavity	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 7		
Comment:	6 Marked, 1 Unmarked (Photo).		
Corrective Action:	Mark unmarked deadman	Date:	08/16/2018
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities			
Facility ID: 266468	Type: WELL	API Number: 071-07824	Status: PR Insp. Status: PR
Producing Well			
Comment:	PR - Calibration Report : (06/08/17) (Photo).		
Corrective Action:	Need to update Calibration Report.	Date:	08/16/2018
Facility ID: 269669	Type: WELL	API Number: 071-07922	Status: PR Insp. Status: PR
Producing Well			
Comment:	PR - Calibration Report : (06/08/17)(Photo).		
Corrective Action:	Need to update Calibration Report.	Date:	08/16/2018

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NO

Pit ID: \_\_\_\_\_

Lat: \_\_\_\_\_

Long: \_\_\_\_\_

Reference Point: \_\_\_\_\_

Other: \_\_\_\_\_

Length: \_\_\_\_\_

Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_

Liner Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: c**Fencing:**

Fencing Type: \_\_\_\_\_

Fencing Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_

Netting Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_

Oil Accumulation: NO2+ feet Freeboard: YESComment: 30' x 70'

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Type: Produced WaterLined: NO

Pit ID: \_\_\_\_\_

Lat: \_\_\_\_\_

Long: \_\_\_\_\_

Reference Point: \_\_\_\_\_

Other: \_\_\_\_\_

Length: \_\_\_\_\_

Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_

Liner Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: c**Fencing:**

Fencing Type: \_\_\_\_\_

Fencing Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_

Netting Condition: \_\_\_\_\_

Comment:			Date:
Corrective Action			
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>	Date:
Comment:	30' x 70'		
Corrective Action			
Monitoring:	Monitoring Type	Comment`	
	Chain	Yellow	
	Chain	Orange	

**COGCC Comments**

Comment	User	Date
SEE : Related Facility : Calibration Report. SEE : Equipment : Unmarked deadman.	duranj	07/17/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401704895	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4525041">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4525041</a>
687902804	Lease sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4525031">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4525031</a>
687902805	Unmarked deadman	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4525032">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4525032</a>
687902806	Well pad	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4525033">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4525033</a>
687902807	Lease sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4525034">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4525034</a>
687902808	Well pad	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4525035">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4525035</a>
687902809	Calibration Report	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4525036">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4525036</a>
687902810	Calibration Report	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4525037">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4525037</a>