

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/17/2018

Submitted Date:

07/17/2018

Document Number:

691200261**FIELD INSPECTION FORM**

Loc ID 327707 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 70385Name of Operator: SMITH ENERGY CORPAddress: 12706 SHILOH RDCity: GREELEY State: CO Zip: 80631**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**15 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Smith, Chris	303-709-6157	smithenergy@live.com	VP; North operations
Smith, Glenn	(970) 381-6253	gsmithten@what-wire.com	
Arthur, Denise		denise.arthur@state.co.us	Reclamation Supervisor

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247257	WELL	PR	05/14/2001	GW	123-15054	CARLSON 22-1	SI

General Comment:

Location

Lease Road:			
Type	Access		
comment:	Access road to Carlson 22-1 (05-123-15054) wellhead is adequate. 2-Track Ag road.		
Corrective ActionL		Date:	
Type	Main		
comment:	Main road to Carlson 22-1 (05-123-15054) is adequate.		
Corrective ActionL		Date:	

Overall Good: ☒

Emergency Contact Number:	
Comment:	<input style="width: 500px; height: 20px;" type="text"/>
Corrective Action:	<input style="width: 500px; height: 20px;" type="text"/> Date: <input style="width: 100px;" type="text"/>

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds around oil tanks, pit, treater, and wellhead. Statewide unused equipment, weeds, waste, and trash requirements.		
Corrective Action:	Comply with Rule 603.f.	Date:	07/27/2018
Type	OTHER		
Comment:	Mechanical conditions. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Gas meter house door is missing.		
Corrective Action:	Comply with Rule 605.d.	Date:	08/16/2018
Type	UNUSED EQUIPMENT		
Comment:	Statewide unused equipment requirements. Unused pumping unit, gas engine, and associated equipment at well.		
Corrective Action:	Comply with Rule 603.f.	Date:	10/15/2018

Overall Good: ☐

Spills:			
Type	Area	Volume	
In Containment: No <input type="text"/>			
Comment: <input style="width: 600px; height: 20px;" type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			

Equipment:			corrective date
Type: Vertical Heater Treater	# 1		
Comment:	<input style="width: 500px; height: 20px;" type="text"/>		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	<input style="width: 500px; height: 20px;" type="text"/>		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		

Comment: 2-phase		Date:
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment: Gas meter run sales line downstream valve is shut. Well appears to not be producing.		Date:
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment: Oil recycle pump connected to vertical heater treater.		Date:
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		Date:
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER		OTHER	PLASTIC AST		,
Comment: H2O tank has drain line going into adjacent earthen pit.					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	10 BBls.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	300 BBLS	STEEL AST		40.480625,-104.198332
Comment: All 4 oil tanks are connected with a 4" equalizer line at top.					
Corrective Action:					Date:

Paint

Condition	Inadequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

<u>Venting:</u>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<u>Flaring:</u>			
Type			
Comment:			
Corrective Action:		Date:	

--

Inspected FacilitiesFacility ID: 247257 Type: WELL API Number: 123-15054 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Well appears to be shut-in at wellhead master valve and gas sales meter run downstream valve.

Corrective Action: _____ Date: _____

BradenHeadComment: Bradenhead appears to be plumbed to surface.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<u>Vertical heater treater door was locked. Needs to be unlocked for follow-up re-inspection.</u>	evinsb	07/17/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401705873	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4525996
691200262	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4525992