

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/17/2018

Submitted Date:

07/17/2018

Document Number:

691200266**FIELD INSPECTION FORM**Loc ID 319086 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	<a href="#">All Inspections</a>
Leonard, Mike		mike.leonard@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242860	WELL	PR	01/01/2014	OW	123-10651	WILDFONG 11-23	PR

**General Comment:**

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Access road to Wildfong 11-23 (API# 05-123-10651) well is adequate. 2-Track Ag road.		
Corrective ActionL		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign not posted at wellhead.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	09/17/2018

Emergency Contact Number:

Comment:	No emergency contact information at wellhead.		
Corrective Action:	Install sign to comply with Rule 210.b.		
	Date:	08/30/2018	

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Prime Mover	# 1		
Comment:	Natural gas engine powers pumping unit.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 242860 Type: WELL API Number: 123-10651 Status: PR Insp. Status: PR**Producing Well**Comment: Well is producing. Pum jack in operation.Corrective Action: Date: **BradenHead**Comment: Bradenhead appears to be plumbed to surface.Corrective Action: Date: **COGCC Comments**

Comment	User	Date
<u>Inspected well only at this time. Didn't inspect battery.</u>	evinsb	07/17/2018

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401705874	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4525997">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4525997</a>
691200267	Site photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4525994">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4525994</a>