

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/19/2018

Submitted Date:

07/24/2018

Document Number:

690100720

**FIELD INSPECTION FORM**

Loc ID 319545 Inspector Name: Maclaren, Joe On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 69175  
Name of Operator: PDC ENERGY INC  
Address: 1775 SHERMAN STREET - STE 3000  
City: DENVER State: CO Zip: 80203

**Findings:**

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Canfield, Chris		chris.canfield@state.co.us	
		cogccinspection@pdce.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243660	WELL	PR	03/01/2018	OW	123-11452	SEEWALD 1-1	EG

**General Comment:**

Engineering integrity inspection performed on July 19th, 2018 in response to initial form 19 spill report Doc #401706484 received by COGCC on 07/18/2018 that outlines: PDC discovered a reportable historical spill while abandoning the battery at the Seewald 1-1 3N68W SESW. Current recovery efforts are mitigating impacts. Details of observations made during this field inspection are available in the flowline and comment sections of this report. Photo's uploaded can be accessed via link(s) at the end of report.

**Inspected Facilities**Facility ID: 243660 Type: WELL API Number: 123-11452 Status: PR Insp. Status: EG**Flowline**

#1	Type:	of Lines	
<u>Flowline Description</u>			
Flowline Type:		Size:	Material:
Variance:		Age:	Contents:
<u>Integrity Summary</u>			
Failures:		Spills:	Repairs Made:
Coatings:		H2S:	Cathodic Protection:
<u>Pressure Testing</u>			
Witnessed:		Test Result:	Charted:
<u>COGCC Rules(check all that apply)</u>			
<input type="checkbox"/> 1101. Installation and Reclamation <input type="checkbox"/> 1102. Operations, Maintenance, and Repair <input checked="" type="checkbox"/> 1103. Abandonment			
<u>Comment:</u>	COGCC inspector met with PDC Energy foreman Dave Hubbs on location. All flowlines associated with the Seewald 1-1 have been removed (wellhead, dump lines & process pipe). Excavation and remediation activities are in progress.		
<u>Corrective Action:</u>			<u>Date:</u>

**COGCC Comments**

Comment	User	Date
Note: DCP Midstream isolated the inactive 2" gas line. The meter run has been removed from location; the gas line riser (on pad) was cut and capped below grade. The tie in to the gathering system has been disconnected (north side of WRC 36).	maclarej	07/24/2018

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690100721	Excavation and remediation activities in progress	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4531771">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4531771</a>
690100722	Gas line isolated at tie in to gathering	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4531774">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4531774</a>