

**Inspection Photos**  
**Location Name: Joker / 36-9-62**  
**Location #: 417683**



**Photo #1**

Joker 36-9-62 (API # 05-123-31719) wellhead

**Stained soil, weeds**

**Bradenhead not plumbed to surface**



**Photo #2**

Joker 36-9-62 (API # 05-123-31719) Battery & Well

**Weeds**



**Inspection Photos**  
**Location Name: Joker / 36-9-62**  
**Location #: 417683**



Colorado Oil & Gas Conservation Commission  
40.70999, -104.27547, 1501.0m, 127°  
2018/07/20 10:12:44 AM

**Photo #3**

Joker 36-9-62 (API # 05-123-31719) Oil & H2O tanks

**Stain on middle tank**



Colorado Oil & Gas Conservation Commission  
40.71034, -104.27526, 1499.0m, 66°  
2018/07/20 10:19:56 AM

**Photo #4**

Joker 36-9-62 (API # 05-123-31719)

**Unused equipment, weeds**

**Inspection Photos**  
**Location Name: Joker / 36-9-62**  
**Location #: 417683**



Colorado Oil & Gas Conservation Commission  
40.71028, -104.27536, 1499.0m, 174°  
2018/07/20 10:08:55 AM

**Photo #5**

Joker 36-9-62 (API # 05-123-31719) Propane tank,  
Treater & Separator

**Weeds**



Colorado Oil & Gas Conservation Commission  
40.71003, -104.27524, 1501.0m, 246°  
2018/07/20 10:11:09 AM

**Photo #6**

Joker 36-9-62 (API # 05-123-31719) Oil & H2O tanks

**Weeds**

**Inspection Photos**  
**Location Name: Joker / 36-9-62**  
**Location #: 417683**



Colorado Oil & Gas Conservation Commission  
40.71024, -104.27508, 1490.0m, 124°  
2018/07/20 01:08:57 PM

**Photo #7**

Joker 36-9-62 (API # 05-123-31719)  
Candlestick Flare



Colorado Oil & Gas Conservation Commission  
40.71012, -104.27494, 1487.0m, 127°  
2018/07/20 01:32:56 PM

**Photo #8**

Joker 36-9-62 (API # 05-123-31719)  
Candlestick Flare battery



**Inspection Photos**  
**Location Name: Joker / 36-9-62**  
**Location #: 417683**



Colorado Oil & Gas Conservation Commission  
40.71012, -104.27496, 1485.0m, 74°  
2018/07/20 01:33:27 PM

**Photo #9**

Joker 36-9-62 (API # 05-123-31719)

Candlestick Flare

**Unhooked spark plug**



Colorado Oil & Gas Conservation Commission  
40.71028, -104.27513, 1486.0m, 169°  
2018/07/20 01:08:43 PM

**Photo #10**

Joker 36-9-62 (API # 05-123-31719) ECD

**Inlet valve is shut. Not in operation**



**Inspection Photos**  
**Location Name: Joker / 36-9-62**  
**Location #: 417683**



**Photo #11**  
Joker 36-9-62 (API # 05-123-31719)  
**Anchors / Markers - Visibility**