

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/26/2018

Submitted Date:

07/27/2018

Document Number:

691200302

FIELD INSPECTION FORM

Loc ID 438160 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10640
Name of Operator: EWS 1 DJ BASIN LLC
Address: 2015 CLUBHOUSE DR SUITE 201
City: GREELEY State: CO Zip: 80634

Findings:

- 7 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Koehler, Bob		bob.koehler@state.co.us	
GODDARD, JIM	(970) 515-6950	jgoddard@expedition-water.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438161	WELL	IJ	02/09/2018	DSPW	123-39891	EWS 1A	AC

General Comment:

(This area is intentionally left blank for general comments.)

Location

Lease Road:			
Type	Main		
comment:	Main road to EWS #1 (API# 05-123-39770) & EWS #1A (API# 05-123-39891) facility is adequate.		
Corrective ActionL		Date:	
Type	Access		
comment:	Access road to EWS #1A (API# 05-123-39891) wellhead is adequate.		
Corrective ActionL		Date:	

Overall Good:

Emergency Contact Number:

Comment:	
Corrective Action:	Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:		corrective date
Type:	#	
Comment:	Refer to FIR# 691200300 for equipment list for this facility.	
Corrective Action:		Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.638770,-104.066350
Comment:	This centralized battery serves locations (437911, 438160). Refer to FIR #691200300 for Tanks & Berms details.				
Corrective Action:				Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:			Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 438161 Type: WELL API Number: 123-39891 Status: IJ Insp. Status: AC

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg 1240 Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: DJINJ
 TC: Pressure or inches of Hg 0 Previous Test Pressure _____ Last MIT: 12/18/2017
 Brhd: Pressure or inches of Hg 0 Previous Test Pressure _____ AnnMTReq: _____

Comment: Well does not have protective shelter. Celler / sump has some stormwater accumulation. Operator informed that water is pumped out as needed.

Corrective Action: _____ Date: _____

Method of Injection: PUMP FEED

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

BradenHead

Comment: Bradenhead appears plumbed to surface.

Corrective Action: _____ Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691200303	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4535152