

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/24/2018

Submitted Date:

07/27/2018

Document Number:

688800232**FIELD INSPECTION FORM**

Loc ID 306806 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 5
 Name of Operator: COLORADO OIL & GAS CONSERVATION
 Address: 1120 LINCOLN ST SUITE 801
 City: DENVER State: CO Zip: 80203

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267716	WELL	AC	02/14/2003	OBW	067-08805	MONITOR WELL 35-6-13-1	EI

General Comment:

On July 24, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the COGCC Monitor Well #35-6-13 #1 (Shamrock Mine). For the most recent field inspection report of this facility, please refer to document #674901761. The purpose of this site visit was to replace the desiccants in the equipment enclosures.

Location

Lease Road:			
Type	Access		
comment:	Locked Forest Service gate on access road.		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign mounted to protective steel cage surrounding well head.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Sign mounted to protective steel cage surrounding well head.		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Locked 4' x 4' x 4' expanded metal and angle iron protective cage surrounding well head.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	In-Situ data logger.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:			Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 267716 Type: WELL API Number: 067-08805 Status: AC Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
On July 24, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the COGCC Monitor Well #35-6-13 #1 (Shamrock Mine). For the most recent field inspection report of this facility, please refer to document #674901761. The purpose of this site visit was to replace the desiccants in the equipment enclosures. The desiccants were last replaced on 6/12/17. All of the battery terminals were free of corrosion.	hughesj	07/27/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800233	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4535822