




**Photo 1. View of the beginning of reclaimed access facing northward.**



**Photo 2. View of a portion of the reclaimed access facing southwestward. Reclamation activities appear to have been conducted. Little germination observed.**



**Photo 3. View of sample quadrat 1. No germination observed within the sample quadrats.**