



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern interim reclamation area from the northwestern corner facing eastward. Vegetation is dry, but appears to be progressing.



Photo 3. View of erosional channels forming within the southern project area. This needs to be monitored and stormwater controls installed if erosion worsens.