

## Inspection Photos

**Location Name:** Federal Osprey- 68N60W / 35NENW

**Location #:** 331181



**Photo #1**

**Federal Osprey 35-3** (API # 05-123-20272) wellhead

**Bradenhead not plumbed to surface**



**Photo #2**

**Federal Osprey 35-3** (API # 05-123-20272) Battery

View 1



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

**Location Name:** Federal Osprey- 68N60W / 35NENW

**Location #:** 331181



**Photo #3**

***Federal Osprey 35-3*** (API # 05-123-20272) Battery

View 2



**Photo #4**

***Federal Osprey 35-3*** (API # 05-123-20272) oil tanks  
load-out

**Stain on ground from previous FIR  
Appears to have cleared**



## Inspection Photos

Location Name: Federal Osprey- 68N60W / 35NENW

Location #: 331181



**Photo #5**

**Federal Osprey 35-3 (API # 05-123-20272) H2O tank**

**Berms dimensions appear inadequate for containment of vessel contents as referenced in previous FIR.**



**Photo #6**

**Federal Osprey 35-3 (API # 05-123-20272) Oil treater**

**Stain on ground from previous FIR remains apparent**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

**Location Name:** Federal Osprey- 68N60W / 35NENW

**Location #:** 331181



**Photo #7**

***Federal Osprey 35-3*** (API # 05-123-20272) oil tanks

**Un-permitted pit referenced from previous FIR  
Remains apparent**





## Inspection Photos

**Location Name:** Federal Osprey- 68N60W / 35NENW

**Location #:** 331181



**Photo #8**

**Federal Osprey 35-3** (API # 05-123-20272) well anchors

**1 - Un-marked anchor referenced from previous FIR  
Remains apparent**



**Photo #9**

**Federal Osprey 35-3** (API # 05-123-20272)

Pumping Unit

**Stain on gearbox from previous FIR  
remains apparent**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

**Location Name:** Federal Osprey- 68N60W / 35NENW

**Location #:** 331181



**Photo #10**

**Federal Osprey 35-3** (API # 05-123-20272)

Pumping Unit

**Stain on ground near skid referenced from previous FIR  
Remains apparent**



**Photo #11**

**Federal Osprey 35-3** (API # 05-123-20272)

Gas Engine – Prime Mover



## Inspection Photos

Location Name: Federal Osprey- 68N60W / 35NENW

Location #: 331181



**Photo #12**

**Federal Osprey 35-3** (API # 05-123-20272)

Gas Engine – Prime Mover

**Stain on ground near skid  
referenced from previous FIR  
Remains apparent**



**Photo #13**

**Federal Osprey 35-3** (API # 05-123-20272)

Gas Engine – Prime Mover

**No engine muffler  
referenced from previous FIR  
Remains apparent**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

**Location Name:** Federal Osprey- 68N60W / 35NENW

**Location #:** 331181



**Photo #14**

**Federal Osprey 35-3** (API # 05-123-20272) wellhead

**Ground oil stains near wellhead**

**referenced from previous FIR**

**Appear to have cleared**



**Photo #15**

**Federal Osprey 35-3** (API # 05-123-20272) wellhead

**Tubing & Rods have been pulled from well**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

**Location Name:** Federal Osprey- 68N60W / 35NENW

**Location #:** 331181



**Photo #16**

***Federal Osprey 35-3*** (API # 05-123-20272) wellhead

**Observed Crystal brand digital gauge on wellhead**

