

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/25/2018

Submitted Date:

07/30/2018

Document Number:

688000165

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: YOUNG, ROB On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 7800
Name of Operator: BEREN CORPORATION
Address: 2020 N BRAMBLEWOOD STREET
City: WICHITA State: KS Zip: 67206

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|--------------|--------------------------|---------|
| Reynolds, Rodney | 316-337-8340 | reynoldsr@berexco.com | |
| Axelson, John | | john.axelson@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|---------|---------------|-------------|
| 111968 | PIT | AC | | | - | BREWER "A" | EI |

General Comment:

Environmental inspection related to Rem #10290, closure of the former northern produced water pit. Pit is currently being backfilled incrementally as groundwater levels allow. A small berm has been constructed on the southern side of the location to prevent groundwater and stormwater from moving off site and down drainage onto the surface of the former southern produced water pit 111969.

Inspected Facilities

Facility ID: 111968 Type: PIT API Number: - Status: AC Insp. Status: EI

Environmental

Spill/Remediation:

Comment: Continue backfilling the former produced water pit as previously approved. If oily waste is encountered during the backfilling, segregate the oily waste and properly store on site for subsequent landfill disposal. Continue to ensure that the water in the former pit is not displaced outside the pit by backfill material and/or stormwater.

Corrective Action:

Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 111968 Lat: 40.654951 Long: -103.278531

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: Former produced water pit is being backfilled.

Corrective Action

Date: c

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 688000166 | Location photographs | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4537549 |