

Inspection Photos  
Location Name: Kowach 1-9  
API: 05-081-06185



**Photo 1. Overview of location taken at entrance facing northwest.**

**Inspection Photos**  
**Location Name: Kowach 1-9**  
**API: 05-081-06185**



**Photo 2. Fluid in cellar being drained out.**



**Photo 3. Drain pathway out of cellar.**

**Inspection Photos**  
**Location Name: Kowach 1-9**  
**API: 05-081-06185**



**Photo 4. Fluid draining out of cellar toward pumpjack stored on location.**



**Photo 5. Drain pathway out of cellar, stained soil where fluid has evaporated.**