



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern interim reclamation area from the northwestern corner facing eastward. Vegetation is dry, but appears to be progressing.



Photo 3. View of the western portion of the project area from the northwestern corner facing southward.



Photo 4. View of single individual Russian knapweed along the southeastern edge of the project area. Russian knapweeds appear to have been treated. Scattered individuals remain.