



Photo 1. View of the reclaimed project area from the northeastern corner facing center. Area is in process of reclamation, but little germination observed.



Photo 2. View of the northern portion of the project area from the northeastern corner facing westward. Facilities in background appear to be associated with pipeline right of way.



Photo 3. View of the eastern portion of the project area from the northeastern corner facing southward.



Photo 4. View of reclaimed portion of project area where facilities were located southeast of the well pad.