

Inspection Photos
Location Name: Duncan Unit 2 1
API: 05-081-05546



Photo 1. Overview of location taken at entrance facing southeast.