

Inspection Photos
Location Name: Duncan 5
API: 05-081-07064



Photo 1. Overview of location taken at entrance facing northeast.