

Inspection Photos

Location Name: Federal Plover - 68N60W / 28SWNW

Location #: 331082



Photo #1

Federal Plover 28-5 X (API # 05-123-20126) wellhead

Flowline is closed & locked.

Bradenhead is plumbed to surface



Photo #2

Federal Plover 28-5 X (API # 05-123-20126) wellhead

View 2



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Federal Plover - 68N60W / 28SWNW

Location #: 331082



Photo #3

Federal Plover 28-5 X (API # 05-123-20126) wellhead

Unmarked deadman anchor



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources