

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/02/2018

Submitted Date:

08/02/2018

Document Number:

689301642**FIELD INSPECTION FORM**

Loc ID 335158 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:19 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Aaron, Axelson	230-0926	aaxelson@vnrenergy.com	Sr. Production Foreman
Ghan, Scott	970-744-8128	sghan@vnrenergy.com	SR. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293142	WELL	PR	05/08/2008	GW	045-14908	SNYDER 24A-26-692	PR
293162	WELL	PR	04/26/2008	GW	045-14910	SNYDER 34A-26-692	PR
293163	WELL	PR	05/08/2008	GW	045-14911	SNYDER 24B-26-692	PR
293164	WELL	PR	04/26/2008	GW	045-14912	SNYDER 34B-26-692	PR
293165	WELL	PR	04/23/2008	GW	045-14913	SNYDER 24C-26-692	PR
293166	WELL	PR	05/03/2008	GW	045-14914	SNYDER 34C-26-692	PR
293167	WELL	PR	04/29/2008	GW	045-14915	SNYDER 24D-26-692	PR
293168	WELL	PR	05/07/2008	GW	045-14916	SNYDER 34D-26-692	PR

General Comment:[Routine Field Inspection](#)

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☒

Emergency Contact Number:

Comment: 1-800-921-8252

Corrective Action:

Date:

Good Housekeeping:

Type	WEEDS		
Comment:			
Corrective Action:		Date:	
Type	TRASH		
Comment:			
Corrective Action:		Date:	
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Hog panel fencing		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Livestock gates		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Ancillary equipment	# 2		
Comment:	Chemical units at wellheads		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 5		
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 8		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:	Water line header		
Corrective Action:			Date:
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	OTHER	STEEL AST		,	
Comment:	375 BBL Tank					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	4	OTHER	HEATED STEEL AST		,	
Comment:	375 BBL tanks Centralized battery					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

<u>Venting:</u>					
Yes/No	YES				
Comment:	Bradenheads open, 14912 has a 500 gallon tank for liquids.				
Corrective Action:					Date:

<u>Flaring:</u>					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	293142	Type:	WELL	API Number:	045-14908	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	293162	Type:	WELL	API Number:	045-14910	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	293163	Type:	WELL	API Number:	045-14911	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	293164	Type:	WELL	API Number:	045-14912	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	293165	Type:	WELL	API Number:	045-14913	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	293166	Type:	WELL	API Number:	045-14914	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	293167	Type:	WELL	API Number:	045-14915	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	293168	Type:	WELL	API Number:	045-14916	Status:	PR	Insp. Status:	PR

Producing Well			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Sediment Traps						
Berms						
				Material Handling And Spill Prevention		
Ditches						
		Compaction				
Rip Rap						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689301643	Inspection Photo 689301643	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4542022