

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/26/2018

Submitted Date:

07/27/2018

Document Number:

685305091

**FIELD INSPECTION FORM**

Loc ID 326144 Inspector Name: St John, William (Cal) On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

**Findings:**

- 25 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">SW Inspection Reports</a>
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215941	WELL	PR	06/10/1991	GW	067-07546	TINKER 02-09 1	PR

**General Comment:**

[Inspection completed as routine inspection requirement.](#)

[This inspection does not alleviate requirement to complete any open corrective actions from previous inspections.](#)

[See link at end of report for path to downloadable pictures.](#)

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:	Dirt and gravel access road.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Framed metal sign at entrance.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Stand alone sign at production tank.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Operator contact information posted on wellhead sign.		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Rack and fencing inside fencing in NE corner. Expanded metal panels on E perimeter outside fencing.		
Corrective Action:	Remove unused equipment to comply with Rule 603.f.	Date:	08/27/2018
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	OTHER		
Comment:	Telemetry equipment - Stock panel fencing.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Water can and valve set - Steel post and pole barrier.		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Chain link fencing topped with barb wire.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Stock panel fencing. Includes production tank.		
Corrective Action:		Date:	

Type	PUMP JACK		
Comment:	<a href="#">Steel mesh safety barrier.</a>		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	<a href="#">Stock panel fencing.</a>		
Corrective Action:		Date:	
<b>Equipment:</b>			corrective date
Type: Other	# 2		
Comment:	<a href="#">Water can and valve set.</a>		
Corrective Action:		Date:	
Type: Flow Line	# 3		
Comment:	<a href="#">In use - 4" steel line from wellhead casing and tubing to separator inlet. All points co-located.</a> <a href="#">In use - 3" steel line from separator outlet to gas meter inlet. All points co-located.</a> <a href="#">In use - 1" steel supply line from separator outlet to tank battery. All points co-located.</a>		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	<a href="#">Electric motor.</a>		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	<a href="#">Steel building with water transfer equipment.</a>		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 0		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	<a href="#">Electrical control equipment.</a>		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	<a href="#">Wellhead.</a>		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	<a href="#">Electrical supply equipment.</a>		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	<a href="#">Telemetry equipment.</a>		

Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	HEATED STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 215941 Type: WELL API Number: 067-07546 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: Revegetation of interim reclamation area is progressing with mixed vegetation.

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Pass					
Rip Rap	Pass					
Gravel	Pass	Gravel	Pass			
Berms	Pass					
Compaction	Pass	Compaction	Pass			

Comment: Stormwater BMPs appear to functioning at time of inspection. Waddles inside fencing on E perimeter are 50% full on the backside.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401717589	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4535771">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4535771</a>
685305101	Inspection photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4535757">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4535757</a>