

Inspection Photos

Location Name: Sooner Unit - 68N58W / 28NWSE

Location #: 319078



Photo #1

Sooner 10-28 (API 05-123-10637)

UIC injection wellsite



Photo #2

Sooner 10-28 (API 05-123-10637)

UIC injection well

Bradenhead has been plumbed to surface

Inspection Photos

Location Name: Sooner Unit - 68N58W / 28NWSE

Location #: 319078



Photo #3

Sooner 10-28 (API 05-123-10637)

Unmarked deadman / anchor

