

Inspection Photo
Boulton 33-8A (G33NE)
API # 045-10264
Inspection # 689301679



Location Photo #1



Location Photo #2



Inspection Photo
Boulton 33-8A (G33NE)
API # 045-10264
Inspection # 689301679



Location Photo #3



Location Photo #4, Oil stained rock in tank containment.

Inspection Photo
Boulton 33-8A (G33NE)
API # 045-10264
Inspection # 689301679



Location Photo #5, Oil stained rock in tank containment.



Location Photo #6, Stained rock in tank containment.

Inspection Photo
Boulton 33-8A (G33NE)
API # 045-10264
Inspection # 689301679



**Location Photo #7, Holes in secondary
containment liner.**