

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/09/2018

Submitted Date:

08/13/2018

Document Number:

679701024**FIELD INSPECTION FORM**
 Loc ID _____ Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10598Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLCAddress: 123 ROBERT S KERR AVECity: OKLAHOMA CITY State: OK Zip: 73102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Deranleau, Greg		greg.deranleau@state.co.us	
Inspections, General		sandridgeenvironmental@sandridgeenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456513	SPILL OR RELEASE	AC	08/08/2018		-	9552 Poudre Canyon Road	EI

General Comment:[COGCC inspection of truck accident spill location and sampling of nearby Maynard water well](#)

Environmental**Spill/Remediation:**

Comment: COGCC inspection of spill 456513 in conjunction with water well sampling performed by COGCC on request of residents adjacent the truck crash and spill. Conditions in the spill area have not changed since Inspection 685100498 by K. Neidel on 8/6/2018. Form 19 Initial Report received 8/8/2018. Form 19 Supplemental Report received 8/13/2018 and in review by COGCC. Corrective actions or required remedial actions will be given by COGCC during review of the Form 19.

Corrective Action:

Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

COGCC Comments

Comment	User	Date
COGCC sample of Breckenridge Water Well (COGCC Facility 759810 - Breckenridge 12571): DWR Receipt, Permit 12571. COGCC arrived onsite at 11:00 a.m. to meet Mr. Breckenridge. Sample was collected from outside faucet which bypassed pressure tank and filters. 11:10 a.m. well purging began at approximately 5 gallons per minute. Water has a heavy orange and turbid color that eventually began to clear. Sample was collected at 11:45 a.m. Samples had an pale orange color. Minimal sulfur odor and no effervescence observed. Sample delivered to ALS Fort Collins. Chain of Custody and sample pictures are attached to this inspection.	allisonr	08/13/2018
COGCC sample of Maynard Water Well (COGCC Facility 759809 - Maynard 275118): DWR Receipt 3619278, Permit 275118. COGCC arrived onsite at 10:00 a.m. to meet Mr. Maynard. At 10:10 a.m. water faucets were opened to flush system. Sample ultimately collected from outdoor hydrant that collects water pumped to the house which is uphill from the well. Water gravity feeds back to hydrant. Well Lat/Lon = 40.68904 / -105.29769. Sample was collected at 10:50 a.m. Water was clear and odorless with no effervescence. Sample delivered to ALS Fort Collins. Chain of Custody and sample pictures are attached to this inspection.	allisonr	08/13/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679701025	Breckenridge sample Chain of Custody	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4550053
679701026	Maynard sample Chain of Custody	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4550054
679701027	Maynard Water Well Sample Photos 8-9-2018	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4550055
679701028	Breckenridge Water Well Sample Photos 8-9-2018	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4550056
679701029	Spill Area Field Photos 8-9-2018	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4550057