



Photo 1. View of the eastern cut-slope from the southeastern corner facing northward. Erosional blanket is installed.



Photo 2. Another view of cut-slope with recently installed blanket. Portions of blanket are torn and insufficiently anchored.



Photo 3. View of the western portion of the project area from the southwestern corner facing northward.



Photo 4. View of the northeastern cut-slope showing areas that are not stabilized with jute mat.



Photo 5. Another view of northeastern cut-slope showing areas that are not stabilized. Trees on the slope have either fallen or have exposed roots from erosion. Additional stabilization measures are needed to stabilize these areas, especially at the top of the slope.