

Final Reclamation Inspection

July 26, 2018

Operator: SRC ENERGY INC- #10311

Location ID: 333039

Inspection Document #: 682403833

Weld County, CO

SESE Section 31 T6N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: LOWE-66N66W /31SESE

Location ID: 333039



Photo 1. Photo taken from the entrance of the location, facing West. Operator failed to reclaim the approach entrance to the location. Stormwater erosion was also observed along the approach entrance. Operator indicated on August 14, 2018 that stormwater erosion was fixed. A follow-up stormwater inspection will be conducted to ensure compliance with Rule 1002.f. standards.

Inspection Photos

Location Name: LOWE-66N66W /31SESE

Location ID: 333039



Photo 2. Photo taken of the eastern location, facing South. Appears the Operator has performed final reclamation activities. No equipment was observed at the location. Germination was sparse throughout the disturbance area and will remain in-process until the location meets Rule 1004 standards.