

# Interim Reclamation Inspection

July 30, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP- #47120

Location ID: 439944

Inspection Document #: 682403848

Weld County, CO

NESE Section 22 T2N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: TAIPAN /27C-15HZ  
Location ID: 439944



**Photo 1.** Photo taken of the southeastern interim area, facing East. Appears the Operator has performed interim reclamation activities to reduce disturbance areas only needed for production operations. Interim areas consists mostly of weedy, annual vegetation. Reference areas appears to be cropland but it does not appear any crops have been planted yet.



Inspection Photos  
Location Name: TAIPAN /27C-15HZ  
Location ID: 439944



**Photo 2.** Photo taken of the southwestern interim area, facing West. See comments under Photo 1.



Inspection Photos  
Location Name: TAIPAN /27C-15HZ  
Location ID: 439944



**Photo 3.** Photo taken of the northeastern interim area, facing South. See comments under Photo 1.



Inspection Photos  
Location Name: TAIPAN /27C-15HZ  
Location ID: 439944



**Photo 4.** Photo taken of the western interim area, facing East. Photo illustrates interim areas have been reduced to only areas needed for production operations.





**Photo 5.** Photo taken along a portion of the access road. Photo illustrates a List B Colorado Noxious weed, Scotch thistle. Appears the Operator was managing weeds at the location but a few still need to be controlled.



Inspection Photos  
Location Name: TAIPAN /27C-15HZ  
Location ID: 439944



**Photo 6.** Reference photo taken southeast of the location, facing North. Appears the reference areas were a wheat crop but nothing has been planted yet.