

# *Inspection Photos*

*API#045-06481*

*Operator: Maralex*

*Inspection Number: 692400004*

*Inspection Date: 7/31/2018*





Photo#1:  
Overview of Location from to West. Note Knapweed indicated by arrow

July 31, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Maralex Albertson API#045-06376



Photo#2:

B list Noxious weed, Russian Knapweed, indicated by arrow is established on Location.

July 31, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Maralex Albertson API#045-06376



**Photo#3:**

There are holes in netting that is layered on panels, allowing ingress of smaller Wildlife, who even though Pit is dry at this time would not be able to find egress.

July 31, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Maralex Albertson API#045-06376



Photo#4:  
Knapweed is established on access road.

July 31, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Maralex Albertson API#045-06376



**Photo#5**

Stormwater is undercutting Rip Rap at NW side of acces road culvert & eroding ditch.

July 31, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Maralex Albertson API#045-06376



**Photo#6:**

Stormwater is undercutting Rip Rap at NW side of access road culvert & eroding down gradient ditch.

July 31, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Maralex Albertson API#045-06376