

Inspection Photos

Loc#430698

Operator: Maralex

Inspection Number: 692400006

Inspection Date: 7/31/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
View over Location from Entry to North.

July 31, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Maralex Compressor Station Loc#430698




Photo#2:
Russian thistle on road, in interim Reclamation & equipment areas.

July 31, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Maralex Compressor Station Loc#430698



Photo#3: Poverty sumpweed

Majority of Vegetation within Interim Reclamation Area is Russian thistle, Kochia, Marsh elder & Poverty sumpweed that are not acceptable Vegetative cover.



Photo#4: Marsh Elder.

July 31, 2018




Photo#5:
View of Compressor & Sound Wall; note weeds growing in and around equipment.

July 31, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Maralex Compressor Station Loc#430698



Photo#6:
View of Sound Wall from North end. :



Photo#7:
View of Sound Wall from South end.
Insert is of back side of compressor & Sound Wall.

July 31, 2018



Photo#8:
Weeds growing in and around equipment.



Photo#9:

July 31, 2018



Photo#10:

Views of dead & growing weeds on berms and in Tank area. Insert is of tank label missing Capacity and Contents.

Photo#11:

July 31, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Maralex Compressor Station Loc#430698



Photo#12:

Mature weeds (Knapweed) have been cut off, left on site & now dead, have become Debris.



Photo#13:

July 31, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Maralex Compressor Station Loc#430698



Photo#14:
Staining and impacted soil were observed around multiple pieces of equipment.



Photo#15:

July 31, 2018



Photo#16:
Staining and impacted soil were observed around multiple pieces of equipment.



Photo#17:

July 31, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Maralex Compressor Station Loc#430698



Photo#18:
Staining and impacted soil were observed around multiple pieces of equipment.



Photo#19:

July 31, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Maralex Compressor Station Loc#430698



Photo#20:

Gaps in netted panel that covers stock tank used for fluid storage from separator unit, allows ingress of smaller Wildlife.

July 31, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Maralex Compressor Station Loc#430698