



Photo 1. View of the project area from the western corner facing center.



Photo 2. View of the southwestern portion of the project area from the southern corner facing northwestward. Rock check dams appear to be functioning. Vegetation is becoming established on fill slopes with grasses, shrubs, and forbs such as smooth brome (*Bromus inermis*), snowberry (*Symphoricarpos albus*), and mules ears (*Wyethia* sp.).



Photo 3. View of Canada thistles (*Cirsium arvense*) within the southern silt trap.



Photo 4. View of the southeastern portion of the project area from the southern corner facing northeastward.



Photo 5. View of green plastic netting debris on the eastern fill slope revegetation area.



Photo 6. View of the northeastern portion of the project area rock run-down appears to be functioning.



Photo 7. View of topsoil storage in the northern portion of the project area.