

Inspection Photos
Location Name: Elk Springs Unit 1-17
API: 05-081-06779



Photo 1. Overview of location taken at entrance facing northeast.



Photo 2. Stained soil and fresh gravel at wellhead. 3 – 1” and 1 – 2” steel risers on right side of wellhead.