

Inspection Photos
Well Name: Horseshoe Canyon 5
Location ID: 312445



Photo 1. Gravel added to area of erosion and sediment migration. Continued monitoring will be necessary to determine if it is effective.



Photo 2. Gravel added to area of erosion and sediment migration. Continued monitoring will be necessary to determine if it is effective.

Inspection Photos
Well Name: Horseshoe Canyon 5
Location ID: 312445



Photo 3. Equipment, supplies and debris still on location.



Photo 4. Equipment, supplies and debris still on location.