

Location

Lease Road:			
Type	Access		
comment:			
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign has been installed resolving the CA referenced in FIR #691200266 & FIRR #401724033.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Emergency contact number has been posted resolving the CA referenced in FIR #691200266 & FIRR #401724033.		
Corrective Action:			Date:

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Natural gas engine powers the pumping unit		
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 242860 Type: WELL API Number: 123-10651 Status: PR Insp. Status: PR

Producing Well

Comment: PR. Pump jack in operation.

Corrective Action:

Date:

BradenHead

Comment: Bradenhead appears to be plumbed to surface.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
This is an AMI inspection. The CA items referenced in FIR #691200266 & FIRR #401724033 have been addressed & resolved. Verified by photo submitted by Operator.	evinsb	08/15/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691200337	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4552993