



**Location**

**Lease Road:**

Type	Access		
comment:			
Corrective ActionL			Date:
Type			
comment:			
Corrective ActionL			Date:

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:			Date:

**Emergency Contact Number:**

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>		Date: _____

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 244420 Type: WELL API Number: 123-12214 Status: PR Insp. Status: WK

**Workover**

Comment: Producer verification of casing repairs with a COGCC witnessed MIT.  
 Results of MIT were as follows:  
 Beginning: 0# on Casing. Pressure was brought upto 1025 psi. Stabilized at 1025# in 2 minutes.  
 5 min interval: 1025#  
 10 min interval: 1025#  
 15 min interval: 1025#  
 Bled pressure down to 0 psi and concluded MIT.

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
See attached Form 21(MIT) that is referenced to this FIR #691200338.	evinsb	08/15/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691200339	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4553103">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4553103</a>