

Interim Reclamation and Stormwater Inspection

August 10, 2018

Operator: BURLINGTON RESOURCES OIL & GAS LP- #26580

Location ID: 429810

Inspection Document #: 682403873

Arapahoe County, CO

SWNW Section 30 T4S R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: WATKINS /30-5-5H H
Location ID: 429810



Photo 1. Photo taken from the entrance of the location, facing West. Photo illustrates a weedy area which may have been the soil stockpile area. Germination of grass species was observed within the weed growth but Operator shall control and manage weeds per Rule 1003 standards.

Inspection Photos
Location Name: WATKINS /30-5-5H H
Location ID: 429810



Photo 2. Photo taken from the eastern interim area, facing North. Operator has failed to manage and control Kochia and Russian thistle throughout the interim area. Germination of grass species was observed within the weed growth but an assessment was not made throughout due to the high density of weeds.

Inspection Photos
Location Name: WATKINS /30-5-5H H
Location ID: 429810



Photo 3. Photo taken from the eastern perimeter of the location, facing East. Sediment basin appears to be properly functioning. No sediment discharge was observed off location.

Inspection Photos
Location Name: WATKINS /30-5-5H H
Location ID: 429810



Photo 4. Photo taken from the northern interim area, facing West. See comments under Photo 2.

Inspection Photos
Location Name: WATKINS /30-5-5H H
Location ID: 429810



Photo 5. Photo taken from the western production area, facing South. Appears Operator has recently removed equipment (separators). Operator shall remove any unused equipment not necessary for production operations.

Inspection Photos
Location Name: WATKINS /30-5-5H H
Location ID: 429810



Photo 6. Photo taken from the eastern production area. Wildlife screen does not appear to be centered. Operator shall comply with Rule 605.b.(7).