

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/06/2018

Submitted Date:

08/09/2018

Document Number:

685100498**FIELD INSPECTION FORM**

Loc ID	Inspector Name:	On-Site Inspection	<input type="checkbox"/>	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 2 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
	NEIDEL, KRIS	2A Doc Num:		

Operator Information:OGCC Operator Number: 10598Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLCAddress: 123 ROBERT S KERR AVECity: OKLAHOMA CITY State: OK Zip: 73102**Contact Information:**

Contact Name	Phone	Email	Comment
James, Michael		sandridgeenvironmental@san dridgeenergy.com	
Axelson, John		john.axelson@state.co.us	
Allison, Rick		rick.allison@state.co.us	
Deranleau, Greg		greg.deranleau@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456513	SPILL OR RELEASE	AC	08/08/2018		-	9552 Poudre Canyon Road	EI

General Comment:

COGCC Environmental staff (Kris Neidel) inspected number 456513 on 8/6/2018. The weather was cloudy with very light rain and 75 degs. No residents or response crew were on location at the time of inspection. Some damage to residential fencing and road signage was observed. Much of the spill path was covered with plastic liner, the covered spill path was approximately 150 feet long. The liner was not disturbed or removed as a part of this inspection. Since the plastic was on the ground, not all of the spill path was observable. Potholes of soil were placed on the liner to hold the liner down. There was no free fluid observed. Soil in the spill area appeared similar in moisture content of adjacent soil. Some dark soil staining was observed in the following areas; 10 feet above the "Poudre Park" sign, to 10 feet below the "Poudre Park" sign, and north (up river) of the residential driveway (near the downed fence). There was evidence of minor surface flow in the soil where staining was observed, all evidence of surface flow was centered around the "Poudre Park" sign and appeared to be about 20 feet above and 20 feet below the sign. Sandridge should continue to work with Rick Allison and COGCC staff to remediate spill area. See Photos attached, All Photos taken by Kris Neidel on 8/6/2018.

Environmental**Spills/Releases:**

Type of Spill: FLOWBACK

Estimated Spill Volume: 130

Comment: Estimated Spill Volume is estimated on the size of the truck and what was reported remaining in the truck.

Corrective Action: Continue to work with COGCC staff, Rick Allison to document spill remediation.

Date: 08/09/2018

Reportable: YES

GPS: Lat

Long

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

Lat

Long

DWR Receipt Num:

Owner Name:

GPS :

Field Parameters:

Sample Location:

Comment:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401728506	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4547637
685100499	photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4547636