

Well Name : Marquez A 1  
API # : 007-06165



Photo 1: New wellhead sign.



Photo 2: Wellhead sign from previous inspection.

Well Name : Marquez A 1  
API # : 007-06165



Photo 3: Cleaned up area at rear of pump jack.



Photo 4: Impacted soil and gravel at rear of pump jack from previous inspection.

Well Name : Marquez A 1  
API # : 007-06165



Photo 5: Cleaned up area at old exhaust outlet.



Photo 6: Impacted soil and gravel at exhaust outlet from previous inspection.

Well Name : Marquez A 1  
API # : 007-06165



Photo 7: Cleaned up area at lube oil tank.



Photo 8: Impacted soil and gravel at lube oil tank previous inspection.

Well Name : Marquez A 1  
API # : 007-06165



Photo 9: Repaired erosion channel.



Photo 10: Erosion channel at front of rock run down from previous inspection.

Well Name : Marquez A 1  
API # : 007-06165



Photo 11: Debris removed from S perimeter.



Photo 12: Vehicle frame in S perimeter from previous inspection.

Well Name : Marquez A 1  
API # : 007-06165



Photo 13: Location overview current inspection.



Photo 14: Location overview current inspection.

Well Name : Marquez A 1  
API # : 007-06165



Photo 15: Location overview current inspection.



Photo 16: Location overview current inspection.