

Well Name : Argenta Fee 18  
API # : 007-06049



Photo 1: Argenta 19 wellhead sign.



Photo 2: Argenta 18 wellhead sign.

Well Name : Argenta Fee 18

API # : 007-06049



Photo 3: Unreadable chemical tank label and missing filler cap at the Argenta 18.



Photo 4: Unreadable chemical tank label at the Argenta 19.



Well Name : Argenta Fee 18

API # : 007-06049



Photo 5: Impacted soil and gravel at rear of pump jack.



Photo 6: Weeds inside fencing at Argenta 18.

Well Name : Argenta Fee 18

API # : 007-06049



Photo 7: Weeds and dried cheat grass inside production equipment fencing.



Photo 8: Steel 1" cable in perimeter of location.



Well Name : Argenta Fee 18  
API # : 007-06049



Photo 9: Steel cable in perimeter of location.



Photo 10: Unused production tanks.

Well Name : Argenta Fee 18

API # : 007-06049



Photo 11: Disconnected risers at back of production tank.



Photo 12: Unused 1" steel riser at Argenta 19 wellhead.



Well Name : Argenta Fee 18  
API # : 007-06049



Photo 13: Location overview.



Photo 14: Location overview with anchor marker down and feed troughs visible.

Well Name : Argenta Fee 18

API # : 007-06049



Photo 15: Chemical tank at Argenta 19 missing filler cap.



Photo 16: Leaning lube oil tank at the Argenta 18.