

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/15/2018

Submitted Date:

08/17/2018

Document Number:

690100738

FIELD INSPECTION FORM

Loc ID 336207 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Beardslee, Tom		tom.beardslee@state.co.us	
,		cogccinspections@anadarko.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Whittington, Ellice		ellice.whittington@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249520	WELL	SI	05/01/2017	GW	123-17323	COORS V 6-13	EG
451374	TANK BATTERY	AC	08/27/2014		-	Coors V 6-13 battery	EG

General Comment:

COGCC Inspector met with Anadarko personnel on location (Bret Schissler and Phil Wagner) and witnessed contractors removing and abandoning the flowlines associated with the Coors V 6-13, Coors V 6-13JI and Coors V6-14JI wells. COGCC Inspector and Anadarko personnel were on site daily between 8/13-8/15 and throughout the completion of this field work. Details of the work completed is outlined in the flowline section of this report. Photo's uploaded can be accessed via link(s) at end of report.

Inspected Facilities									
Facility ID:	249520	Type:	WELL	API Number:	123-17323	Status:	SI	Insp. Status:	EG
Facility ID:	451374	Type:	TANK	API Number:	-	Status:	AC	Insp. Status:	EG

Flowline		
#1	Type:	of Lines
<u>Flowline Description</u>		
Flowline Type:	Size:	Material:
Variance:	Age:	Contents:
<u>Integrity Summary</u>		
Failures:	Spills:	Repairs Made:
Coatings:	H2S:	Cathodic Protection:
<u>Pressure Testing</u>		
Witnessed:	Test Result:	Charted:
<u>COGCC Rules(check all that apply)</u>		
<input type="checkbox"/> 1101. Installation and Reclamation <input type="checkbox"/> 1102. Operations, Maintenance, and Repair <input checked="" type="checkbox"/> 1103. Abandonment		
<u>Comment:</u>	The production flowlines were flushed (Coors V6-13, Coors V6-13JI and Coors V6-14JI/ using fresh water and air) on 8/10/18; this work was witnessed by COGCC inspector Tom Beardslee. Starting on 8/13, Anadarko contractors excavated (mechanical and hydro) and exposed flowlines at the wellheads (V6-13 & V6-13JI) and the inlet to the horizontal separator. Additional excavations exposed the flowlines between the end points. The flowlines were unearthed and pulled out of the ground; materials removed from location and discarded. The Coors V6-13 & V6-13JI flowlines were completely removed. The Coors V 6-14JI flowline was removed from Oak Meadows Blvd west to the horizontal separator. Future work is scheduled to remove the remaining section of the Coors V6-14Ji flowline (off location) on property east of Oak Meadows Blvd. In addition, (2) historically abandoned flowlines (1" HDPE and 2" C-Steel) associated with the Coors V 6-13 well were flushed (water & air), unearthed and removed from the property (between the wellhead to Oak Meadows Blvd). Short sections of the 1" and 2" flowlines (approx 28' length) were abandoned in place (per COGCC rule 1105) at/ near the Oak Meadows Blvd road crossing; pipe was cemented and ends sealed/ plugged. Flowline work completed on 8/15/2018 (excavations backfilled/ compacted). Note: Dump lines/ process pipe will be removed from location during the decommissioning of the Coors facility/ battery.	
Corrective Action:	Date:	

COGCC Comments		
Comment	User	Date
Note: DCP Midstream removed the meter run and 3" gas gathering riser/ pipeline (01-P-03-01017) servicing the Coors 6-13 facility; a section of this 3" pipeline (pressurized) was left in place at Colorado Blvd and running approximately 75' east into the property. The endpoint is marked with DCP signage.	maclarej	08/17/2018

Attached Documents		
You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:		
Document Num	Description	URL
690100743	Coors V 6-13, 6-13JI Flowline Removal Abandonmnt	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4555161
690100744	DCP Pipeline leg left in place/ view west to Colo Blvd	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4555162