

Inspection Photos

08/14/2018

Operator: ABILENE PERFECT ENERGY JV LLC -
10581

Location ID: 414589

Inspection Doc. Number: 682503733
Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the south end of the location, facing east. Photo shows what appears to be four (4) bundles of pipe stored on the southern interim area. Previous inspections documented that this is unused equipment not needed for production and that needs to be removed from location. Photo shows equipment has not been removed.

Inspection Photos
Operator: ABILENE PERFECT ENERGY JV LLC - 10581
Location ID: 414589



Photo 2: Photo taken from the west end of the tank battery. Previous inspections documented stained soils within the berm, and that the manway cover has been removed from the tank. Photo shows cover has not been replaced and stained soils remain.



Photo 3: Photo taken from the west end of the location. Previous inspections documented this 5 gallon bucket being used to collect chemicals from equipment and stained soils at the base. Inspections required that equipment needs to be repaired to fix leaks, and bucket needs to be removed and properly disposed or placed in containment. Photo shows bucket and stained soils remain.



Photo 4: Photo taken from the east end of the pump jack, facing west. Previous inspections documented numbers 5 gallon buckets w/ chemical and oil jugs found around pump jack, and required containers to be properly removed and disposed, or placed into containment. Photo shows containers have not been removed or placed into containment.

Inspection Photos
Operator: ABILENE PERFECT ENERGY JV LLC - 10581
Location ID: 414589



Photo 5: See comments under photo 4.



Photo 6: Photo taken from the east end of the pump, facing northwest. Photo shows unused equipment stored on location. Equipment is not needed for production and needs to be removed.



Photo 7: Photo taken from the north end of the well, facing south. Previous inspections documented contaminated soils around well and required stained soils to be cleaned. Photo shows contaminated soils remain.

Inspection Photos
Operator: ABILENE PERFECT ENERGY JV LLC - 10581
Location ID: 414589



Photo 8: Photo taken from the west end of the pump unit, facing south. Previous inspections documented various trash debris on location and interim areas and required removal. Photo shows trash debris remaining.



Photo 9: Photo taken from the north end of the location, facing southwest. Photo shows unused equipment not needed for production remains on location.

Inspection Photos
Operator: ABILENE PERFECT ENERGY JV LLC - 10581
Location ID: 414589



Photo 10: Photo taken from the north end of the location, facing southwest. Photo shows unused equipment not needed for production remains on location. Photo also shows 5 gallon bucket that appears to be empty has not been properly removed and disposed, or placed into containment.

Inspection Photos
Operator: ABILENE PERFECT ENERGY JV LLC - 10581
Location ID: 414589



Photo 11: Photo taken from the north end of the location, facing north. Photo shows unused equipment not needed for production remains on location.



Photo 12: Photo taken from the north end of the location, facing north. Previous inspection documented camper trailer being stored on location. Trailer is not needed for production and was required to be removed. Camper trailer remains. Photo also shows various trash debris around camper trailer.



Photo 13: Photo taken from the north end of the location, facing south. Photo shows various unused equipment not needed for production stored on location.



Photo 14: Photo taken from the north end of the location, facing southwest. Photo shows various unused equipment not needed for production stored on location.



Photo 15: Photo taken from the north end of the location, facing northeast. Photo shows various unused equipment not needed for production stored on location.



Photo 16: Photo taken from the north end of the location, facing west. Photo shows various unused equipment not needed for production stored on location.



Photo 17: Photo taken from the north side of the camper trailer. Photo shows hose that appeared to have been attached to the grey/waste water valve of the camper has been disconnected.



Photo 18: Photo taken from the north side of the camper trailer. Photo shows area where hose attached from camper lead to. Photo also shows various trash debris and unused equipment remaining on location.



Photo 19: Photo taken from the north end of the location. Previous inspections documented 5 gallon buckets w/ chemical and stained soils and required buckets to be properly removed and disposed, or placed into containment and soil cleaned. Photo shows buckets and contaminated soils remain.



Photo 20: Continued from photo 19.

Inspection Photos
Operator: ABILENE PERFECT ENERGY JV LLC - 10581
Location ID: 414589



Photo 21: Photo taken from the northeast corner of the tank battery, facing south. Previous inspections required operator to remove vegetation from the berms of the battery and production equipment; vegetation compromises the integrity of the containment berms. Photo shows vegetation has not been removed.



Photo 22: Photo taken from the northeast corner of the tank battery, facing west. See comments under photo 21.

Inspection Photos
Operator: ABILENE PERFECT ENERGY JV LLC - 10581
Location ID: 414589



Photo 23: Photo taken from the north end of the location, facing north. See comments under photo 21.



Photo 24: Photo taken from the north end of the location. Previous inspections documented stained (E&P waste) soil piled on the north end of the location and required operator to properly treat or dispose. Photo shows pile remains.