

Inspection Photos

Operator: SG Interests

API: 05-051-06059

Date: 7/25/2018



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern portion of the project area from the northeastern corner facing westward.



Photo 3. View of the southern portion of the southwestern corner facing eastward.



Photo 4. View of small pieces of trash in the southern interim reclamation area.



Photo 5. View of trash along the southern edge of the well pad.



Photo 6. View of more small trash on the southern edge of the project area.



Photo 7. View of cut-slope along northeastern edge of project area that is sloughing and eroding. Erosion controls are needed to stabilize this slope.