

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/18/2018

Submitted Date:

08/18/2018

Document Number:

689301766**FIELD INSPECTION FORM**
 Loc ID 335433 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num:
Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Contact Information:**

Contact Name	Phone	Email	Comment
Rocky, TEP		COGCCInspectionReports@terraep.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272558	WELL	PR	11/28/2004	GW	045-10099	FEDERAL RWF 323-19	PR
272559	WELL	PR	12/03/2004	GW	045-10098	FEDERAL RWF 23-19	PR
272788	WELL	PR	12/14/2004	GW	045-10158	FEDERAL RWF 423-19	PR
272789	WELL	PR	12/06/2004	GW	045-10157	FEDERAL RWF 523-19	PR

General Comment:[Corrective action's as specified as required were not met, per Inspection #689301578.](#)

Location					
Lease Road:					
Type	Access				
comment:					
Corrective Action	L				Date:
Overall Good: <input checked="" type="checkbox"/>					
Emergency Contact Number:					
Comment:	1-970-285-9377				
Corrective Action:					Date:
Good Housekeeping:					
Type	DEBRIS				
Comment:	Rebar pile near separators				
Corrective Action:	Comply with Rule 603.f .				Date: 08/02/2018
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type	WELLHEAD				
Comment:	Hog panel fencing				
Corrective Action:					Date:
Type	TANK BATTERY				
Comment:	Hog panel fencing				
Corrective Action:					Date:
Type	SEPARATOR				
Comment:	Hog panel fencing				
Corrective Action:					Date:
Equipment:					
Type: Bird Protectors	# 2				corrective date
Comment:					
Corrective Action:					Date:
Type: Horizontal Heated Separator	# 4				
Comment:					
Corrective Action:					Date:
Type: Plunger Lift	# 4				
Comment:					
Corrective Action:					Date:

Type: Emission Control Device	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLs	STEEL AST		,
Comment:	Centralized battery				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	272558	Type:	WELL	API Number:	045-10099	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	272559	Type:	WELL	API Number:	045-10098	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	272788	Type:	WELL	API Number:	045-10158	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	272789	Type:	WELL	API Number:	045-10157	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
		Gravel				
Compaction						
Hydro Mulch						
Berms						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689301767	Inspection photo 689301767	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4555389