

Inspection Photos

Operator: SG Interests

API: 05-051-06070

Date: 7/26/2018



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western portion of the project area from the northwestern corner facing southward.



Photo 3. View of the northern portion of the project area. Black tubing stored on location.



Photo 4. View of musk thistles that appear to be treated in the northern project area. Some untreated rosettes observed. Subsequent treatments will be needed.