

Inspection Photos

Operator: SG Interests

API: 05-051-06107

Date: 7/25/2018



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern portion of the project area from the southeastern corner facing westward.



Photo 3. View of the eastern portion of the southeastern corner facing northward. Straw blankets and diversion ditch are in place and appear to be functioning at this time.



Photo 4. View of musk thistles that appear to be treated in the southern project area. As many have flowered subsequent treatments will be needed.



Photo 5. View of culvert along access road, appears damaged. If damage is preventing flow, replacement may be needed.



Photo 6. View of the project area from the northeastern corner facing center. Stained soils present on location. Multiple areas with stained soils observed on location.