

Inspection Photos

Operator: Gunnison Energy

API: 05-029-06095

Date: 7/26/2018



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern portion of the project area from the northeastern corner facing westward.



Photo 3. View of the southern portion of the project area from the southwestern corner facing eastward. Vegetation is well established.



Photo 4. View of Canada thistles (*Cirsium arvense*) that do not appear treated with herbicide in the western interim reclamation area.